

JET

BD-X7

METAL LATHE


Original:

GB
Operating Instructions

Translations:

D
Gebrauchsanleitung

F
Mode d'emploi



Walter Meier (Tool) AG

Tämperlistrasse 5
CH-8117 Fällanden
Switzerland

Phone +41 44 806 47 48

Fax +41 44 806 47 58

jetinfo.eu@waltermeier.com

www.jettools.com



Part list

No.	Description	Q'ty	No.	Description	Q'ty
1	Bearing 80206	2	55	Screw M4*10	3
2	Cover	2	56	Screw M6*8	1
3	Screw M5*12	11	57	Nut M4	1
4	Spur Gear	1	58	Screw M4*20	1
5	Nut M27*1.5	2	59	Slide box	1
6	Pully	1	60	Shaft	1
7	Spacer	2	61	Gear	1
8	Screw M6*25	3	62	Groove Cam	1
9	Nut M6	4	63	Nut (Metric)	1
10	Head Stock Casting	1	64	Feeding Gear	1
11	Spindle	1	65	Hand wheel	2
12	Parallel Key 4*28	1	66	Handle	2
13	Washer 6	2	67	Gib strip	1
14	Brushless motor 500W	1	68	Handle nut base	1
15	Spring Washer 5	9	69	Spring	2
16	Screw M5*14	7	70	Support feet	1
17	Pully	1	71	Screw M4*10	2
18	Parallel Key 5*18	1	72	Screw M4*12	3
19	Pully	1	73	Screw M10*50	1
20	Motor connector	1	74	Screw M6*25	9
21	Bracket for motor	1	75	Compound Rest	1
22	Washer 5	7	76	Slider	1
23	Screw M6*10	3	77	Gib strip	1
24	Screw M6*12	6	78	Angle Block	1
25	Nut M5	4	79	Bracket	1
26	Screw M5*10	5	80	Cross Feeding Screw	1
27	Nut M4	6	81	Washer	1
28	Screw M4*16	3	82	Handle	1
29	Screw M4*8	2	83	Positioning Pin	1
30	Screw M4*12	4	84	Tool Rest	1
31	Washer 8	2	85	Handle set	1
32	Spring Washer M6	2	86	Nut M6	1
33	Screw M6*10	4	87	Screw M5*16	1
34	Screw M6*20	2	88	Screw M5*25	1
35	Saddle	1	89	Washer 10	1
36	Press board	2	90	Nut M10	1
37	Cross Slide	1	91	Screw M6*14	1
38	Feeding Screw (Metric)	1	92	Screw M8*40	1
39	Gib Strip	1	93	Tailstock Casting	1
40	Feeding Nut	1	94	Bottom board	1
41	Dial	1	95	Plate of tailstock	1
42	Dial	2	96	Washer	1
43	Handle (big)	1	97	Tailstock Screw	1
44	Orientation	1	98	Flange	1
45	Spring patch	2	99	Tailstock	1
46	Screw M6*16	2	100	Handle	1
47	Steel ball	1	101	Clamp	1
48	Screw M4*10	4	102	Cover	1
49	Nut M8	3	103	Switch label	1
50	Screw M8*55	2	104	Switch	1
51	Round Pin A5*12	1	105	Connector	1
52	Screw M6*12	2	106	Fuse	1
53	Washer	2	107	Screw M4*10	2
54	Screw M4*8	8	108	Yellow Indicator Light	1

No.	Description	Q'ty	No.	Description	Q'ty
109	Switch	1	163	Support Plate	1
110	Power indicator	1	164	Nut M8	1
111	Button	1	165	Shaft	1
112	PC Board	1	166	Feeding Gear	1
113	Cover of motor	1	167	Key	1
114	Screw M5*8	7	168	Gear	2
115	Rubber Pipe	1	169	Screw M5*8	1
116	Label	1	170	Handle sleeve	1
117	Lightning label	1	171	Nut M6	1
118	Defend board	1	172	Fixed board	1
119	Dustproof	1	173	Indicator	1
120	Power line	1	174	Compression Spring	1
121	Left Support	1	175	Board	1
122	Right Support	1	176	Screw M5*66	2
123	Screw M6*20	5	177	Support board	1
124	Parallel key 3*16	1	178	Cover	1
125	Washer	1	179	Chuck	1
126	Screw M3*10	4	180	Filter	1
127	Washer	4	181	Cover	1
128	Screw M6*16	4			
129	Screw M5*20	1			
130	Nut M5	1			
131	Screw M8*25	3			
132	Bed way	1			
133	Long Rack	1			
134	Tray	1			
135	Screw	1			
136	Cover	1			
137	Washer 4	3			
138	Screw M4*6	6			
139	Switch	1			
140	Cover of chuck	1			
141	Cover of switch	1			
142	Screw M3*5	4			
143	Screw M4*30	2			
144	Cover board	1			
145	Screw M3*6	6			
146	Cover	1			
147	Spring washer 12	1			
148	Gear I	1			
149	Feeding Gear	2			
150	Gear II	1			
151	Washer 5	2			
152	Spring washer M5	1			
153	Screw M5*10	1			
154	Fixed Screw	1			
155	Parallel key 3*8	1			
156	Screw	1			
157	Gear support	1			
158	Screw M5*20	2			
159	Parallel key 3*6	1			
160	Gear	2			
161	Washer	2			
162	Support Screw	1			

