

JET

JWDP-12

Drill Press

716000M.....230V 50Hz

PARTS LIST


JPW (Tool) AG
Täumperlistrasse 5
CH-8117 Fällanden
Switzerland
Phone +41 44 806 47 48
Fax +41 44 806 47 58

www.jettools.com




P-716000M 2016-08

Exploded View for JWDP-12 Drill Press



Exploded View for JWDP-12 Drill Press



Parts List for JWDP-12 Drill Press

| Index No | Part No | Description | Size | Qty |
|-----------------|----------------|--|-------------|------------|
| 1 | JWDP12-001 | Base | | 1 |
| 201 | JWDP12-201 | Column Assembly (#2 thru 5) | | 1 |
| 2 | TS-1524011 | Socket Set Screw | M8x8 | 3 |
| 3 | JWDP12-003 | Column Support..... | | 1 |
| 4 | TS-1491031 | Hex Cap Screw..... | M10x25 | 4 |
| 5 | JWDP12-005 | Column | | 1 |
| 6 | JWDP12-006 | Rack | | 1 |
| 7 | JWDP12-007 | Rack Collar | | 1 |
| 202 | JWDP12-202 | Crank Arm Handle Assembly (#8 thru 10) | | 1 |
| 8 | JWDP12-008 | Crank Arm Handle Grip | | 1 |
| 9 | JWDP12-009 | Crank Arm Shaft | | 1 |
| 10 | TS-1523031 | Socket Set Screw | M6x10 | 6 |
| 203 | JWDP12-203 | Table Support Assembly (#11 thru 20, and 123)..... | | 1 |
| 11 | JWDP12-011 | Worm Shaft..... | | 1 |
| 12 | JWDP12-012 | Table Support | | 1 |
| 13 | JWDP12-013 | Helical Gear | | 1 |
| 14 | JWDP12-014 | Gear Pin | | 1 |
| 15 | TS-2361121 | Spring Washer | 12mm | 1 |
| 16 | TS-1492031 | Hex Cap Screw | M12x35 | 1 |
| 17 | JWDP12-017 | Table Arm | | 1 |
| 18 | TS-2284082 | Phillips Screw | M4x8 | 2 |
| 19 | TS-2361041 | Spring Washer | 4mm | 2 |
| 20 | JWDP12-020 | Tilt Scale | | 1 |
| 21 | JWDP12-021 | Lock Handle | | 2 |
| 204 | JWDP12-204 | Handle Assembly (#22 and 23) | | 3 |
| 22 | JWDP12-022 | Knob | | 3 |
| 23 | JWDP12-023 | Handle | | 4 |
| 24 | JWDP12-024 | Pinion Shaft | | 1 |
| 25 | JWDP12-025E | Power Cord | | 4 |
| 26 | JWDP12-026E | LED Bulb | 230V | 1 |
| 27 | JWDP12-027 | Lamp Socket | | 1 |
| 28 | JWDP12-028 | Lamp Socket Bracket | | 1 |
| 29 | TS-2283102 | Phillips Screw | M3x10mm | 1 |
| 30 | TS-1490011 | Hex Cap Screw | M8x12 | 4 |
| 31 | TS-1550061 | Flat Washer | 8mm | 1 |
| 32 | JWDP12-032 | Rack shaft | | 1 |
| 33 | JWDP12-033 | Spring | | 1 |
| 34 | JWDP12-034 | Laser | | 2 |
| 205 | JWDP12-205 | Table Assembly (#35 thru 43) | | 1 |
| 35 | TS-1534042 | Phillips Screw | M6x12 | 1 |
| 36 | TS-1550061 | Flat Washer | 8mm | 1 |
| 37 | JWDP12-037 | Table | | 1 |
| 38 | JWDP12-038 | Locking Knob | | 2 |
| 39 | JWDP12-039 | Guide Bar | | 2 |
| 40 | JWDP12-040 | Roller | | 1 |
| 41 | JWDP12-041 | Roller Support | | 1 |
| 42 | TS-1514011 | Socket Head Flat Screw | M6x12 | 2 |
| 43 | JWDP12-043 | Roller Screw | | 2 |
| 206 | JWDP12-206 | Spindle Assembly (#44 thru 48) | | 1 |
| 44 | JWDP12-044 | Circlip for shaft | C-11 | 1 |
| 45 | BB-6201V | Bearing | 6201RZ | 1 |
| 46 | JWDP12-046 | Quill | | 1 |
| 47 | BB-6204RZ | Bearing | 6204RZ | 2 |
| 48 | JWDP12-048 | Spindle | | 1 |
| 49 | JWDP12-049 | Rubber Washer | | 1 |
| 50 | JWDP12-050 | Drift Key | | 1 |
| 51 | JWDP12-051E | Chuck Arbor | MT2/B16 | 1 |
| 207 | JWDP12-207E | Spindle Speed Adjust Lever (#22 and 135) | | 1 |
| 52 | JWDP12-52E | Keyless Chuck | | 1 |

| Index No | Part No | Description | Size | Qty |
|-----------------|----------------|--|---------------------|------------|
| 62 | JWDP12-062 | Switch for Lamp | | 1 |
| 63 | TS-1533032 | Phillips Screw | M5x10 | 1 |
| 64 | JWDP12-064 | Switch for Laser | | 1 |
| 65 | JWDP12-065E | Switch for Motor | KJD20-2 230V | 1 |
| 66 | TS-1533042 | Phillips Screw | M5x14 | 2 |
| 67 | JWDP12-067E | Switch Box | | 1 |
| 68 | JWDP12-068E | Digital Read Out | | 1 |
| 69 | JWDP12-069 | Self-Tapping Screw | ST2.9x6.5 | 4 |
| 70 | JWDP12-070 | Bushing | | 1 |
| 71 | JWDP12-071 | Spring Retainer | | 1 |
| 208 | JWDP12-208 | Coil Spring Assembly (#72 and 73) | | 1 |
| 72 | JWDP12-072 | Coil Spring | | 1 |
| 73 | JWDP12-073 | Spring Housing | | 1 |
| 74 | JWDP12-074 | Thin Hex Nut | M12 | 2 |
| 209 | JWDP12-209 | Drive Sleeve Assembly (# 75 thru 79) | | 1 |
| 75 | F006045 | External Retaining Ring | 17mm | 1 |
| 76 | JWDP12-076E | Ball Bearing | 61905-2Z | 2 |
| 77 | JWDP12-077E | Spacer | | 1 |
| 78 | JWDP12-078 | Key | A4x4x64 | 1 |
| 79 | JWDP12-079E | Drive Sleeve | | 1 |
| 210 | JWDP12-210 | Spindle Pulley Assembly (#80 thru 86) | | 1 |
| 80 | JWDP12-080 | Spindle Pulley, Lower | | 1 |
| 81 | JWDP12-081 | Spindle Pulley, Upper | | 1 |
| 82 | JWDP12-082 | Retaining Ring | 55mm | 1 |
| 83 | BB-61907RZ | Ball Bearing | 61907RZ | 1 |
| 84 | JWDP12-084 | Bracket | | 1 |
| 85 | F006033 | Internal Retaining Ring | 35mm | 1 |
| 86 | TS-1524031 | Set Screw | M8X12 | 2 |
| 87 | F006049 | External Retaining Ring | 24mm | 1 |
| 88 | JWDP12-088 | Belt | M36 (O-La900) | 1 |
| 89 | TS-1533042 | Phillips screw | M5x12 | 4 |
| 90 | JWDP12-090 | Cord Pressure Plate | | 3 |
| 211 | JWDP12-211 | Motor Pulley Assembly (#91, 92 and 10) | | 1 |
| 91 | JWDP12-91 | Motor Pulley, Lower | | 1 |
| 92 | JWDP12-92 | Motor Pulley, Upper | | 1 |
| 93 | JWDP12-093 | Grommet A | | 1 |
| 94 | JWDP12-094 | Grommet B | | 3 |
| 95 | TS-1482021 | Phillips screw | M6x12 | 4 |
| 96 | JWDP12-096 | Pulley Cover | | 1 |
| 97 | JWDP12-097 | Lock Nut | M10 | 1 |
| 98 | JWDP12-098 | Washer | | 1 |
| 99 | JWDP12-099 | Hub | | 1 |
| 100 | JWDP12-100 | Phillips Screw | M5x10 | 5 |
| 101 | JWDP12-101 | Shaft Plate | | 1 |
| 102 | JWDP12-102 | Shaft | | 1 |
| 103 | JWDP12-103 | Key | A3x3x25 | 1 |
| 104 | JWDP12-104 | Quill Set Screw | M8 | 1 |
| 105 | TS-1540061 | Hex Nut | M8 | 5 |
| 106 | JWDP12-106 | Phillips Screw | M5x8 | 2 |
| 107 | TS-2193051 | Internal Tooth Lock Washer | 5mm | 2 |
| 108 | JWDP12-108 | Pin | 5x13 | 1 |
| 109 | JWDP12-109E | Headstock | | 1 |
| 110 | JVM836-47 | Retaining Ring | C-14 | 1 |
| 111 | JWDP12-111 | Phillips Screw | M4x20 | 2 |
| 112 | JWDP12-112 | Spring Cover | | 1 |
| 113 | JWDP12-113 | Motor Washer | | 1 |
| 114 | JWDP12-114E | Counter | 230V 3.5V | 1 |
| 115 | JWDP12-115 | Counter Base | | 1 |
| 116 | JWDP12-116 | Sponge Pad | | 4 |
| 118 | JWDP12-118 | Wrench | | 1 |

| Index No | Part No | Description | Size | Qty |
|-----------------|----------------|---|-------------------------|------------|
| 119 | TS-152704 | Hex Wrench S3 | S-3 | 1 |
| 120 | TS-152705 | Hex Wrench S4 | S-4 | 1 |
| 121 | JWDP12-121E | Motor Pulley Spring | | 1 |
| 122 | JWDP12-122 | Pin | 6x15 | 2 |
| 123 | JWDP12-123 | Angle Scale | | 1 |
| 124 | TS-152706 | Flat Washer | 8mm | 4 |
| 125 | TS-2361081 | Spring Washer | 8mm | 3 |
| 126 | TS-1490021 | Hex Cap Screw | M8x16 | 4 |
| 127 | JWDP12-127E | Motor Assembly | 550W, 230V, 1Ph | 1 |
| | JWDP12-127ESC | Starting Capacitor (not shown) | 100 μ F, 250V | 1 |
| | JWDP12-127ECC | Capacitor Cover (not shown) | 16uf, 450V | 1 |
| | JWDP12-127ECS | Centrifugal Switch (not shown) | | 1 |
| | JWDP12-127MF | Motor Fan (not shown) | | 1 |
| | JWDP12-127MC | Motor Cover (not shown) | | 1 |
| 128 | JWDP12-128 | Key | A4x4x80 | 1 |
| 129 | JET-92 | Jet Logo | 92x38mm | 1 |
| 130 | LM000139 | Speed Control Label | | 1 |
| 131 | LM000140 | RPM Label | | 1 |
| 132 | LM000141E | ID Label | | 1 |
| 133 | LM000142E | Motor Label | | 1 |
| 134 | LM000143E | Warning Label | | 1 |
| 135 | JWDP12-135E | Spindle Speed Adjust Lever | | 1 |
| 136 | JWDP12-136E | Scale | | 1 |
| 137 | JWDP12-137E | Set Screw | | 1 |
| 138 | JWDP12-138E | Pointer | | 1 |
| 300 | JWDP12-300E | E-Stop Switch Assembly (#301, Thru 312) | | 1 |
| 301 | JWDP12-301E | Switch Push Button | LAY5-BE102 | 1 |
| 302 | JWDP12-302E | Self-Tapping Screw | ST3.2x10 | 4 |
| 303 | JWDP12-303E | Switch Box Cover | | 1 |
| 304 | JWDP12-304E | Switch Box | | 1 |
| 305 | JWDP12-305E | Hex. Cap Screw | M6x25 | 2 |
| 306 | JWDP12-306E | Strain Relief | 6P-4 | 1 |
| 307 | JWDP12-307E | Cord | | 1 |
| 308 | JWDP12-308E | Special Bolt | | 1 |
| 309 | JWDP12-309E | Plastic Tube | | 1 |
| 310 | JWDP12-310E | Plastic Tube Cover | | 1 |
| 311 | JWDP12-311E | Self-Tapping Screw | ST4.2x10 | 4 |
| 312 | JWDP12-312E | Micro Switch | | 1 |
| 313 | JWDP12-313E | Pan Head Machine Screw | M5x8 | 1 |
| 314 | JWDP12-314E | Guard Shaft | | 1 |
| 315 | JWDP12-315E | Guard | | 1 |
| 316 | JWDP12-316E | Washer | 5 | 2 |
| 317 | JWDP12-317E | Hex. Cap Screw | M5x12 | 2 |

Wiring Diagram for JWDP-12 Drill Press

716000M..... ~ 230V, 50Hz

| | colour of strands | Litzenfarben | couleur des cordons |
|------|-------------------|--------------|---------------------|
| BK | black | schwarz | noir |
| WH | white | weiß | blanc |
| BU | blue | blau | bleu |
| RD | red | rot | rouge |
| BN | brown | braun | brun |
| GY | grey | grau | gris |
| GNYE | green-yellow | grün-gelb | vert-jaune |

| | meaning of symbol | Bedeutung der Zeichen | interprétation |
|----|-----------------------|------------------------|------------------------|
| M | motor | Motor | moteur |
| S | switch | Schalter | interrupteur |
| C1 | Condenser of running | Kondensator | condensateur |
| C2 | Condenser of Starting | Kondensator | condensateur |
| n | centrifugal switch | Fliehkraftschalter | déclencheur centrifuge |
| OL | overload cut-off | Überlastschutzschalter | déclencheur surcharge |
| LS | limit switch | Positionendschalter | micro |
| SB | E-stop | Not-Aus Taster | arrêt d'urgence |

